Common Sanitary Defects and Possible Corrective Actions For Mississippi Public Water Supplies

Common Cause	Common Corrective Action(s)
Failure to disinfect (or improper disinfection) after maintenance work in the distribution system	• Disinfection
Main breaks	 Disinfection Replacement/repair of distribution system components
Holes in storage tank, inadequate screening, etc.	 Maintenance of storage facility Addition of security measures Development & implementation of an operations plan
Cracks in well seal, casing, etc.	Replacement/repair of well components
Loss of system pressure	 Maintenance of adequate pressure Valve maintenance Addition or upgrade of on-line monitoring & control
Biofilm accumulation in the distribution system	FlushingMaintenance of adequate pressure
Cross connections	 Maintenance of adequate pressure Installation of backflow prevention assembly/device Implementation/upgrade of cross connection control program
Inadequate disinfectant residual	 Disinfection Flushing Maintaining appropriate hydraulic residence time Addition or upgrade of on-line monitoring & control
Contaminated sampling taps	 Replacement/repair of distribution system components Sampler training
Sampling protocol errors	 Sampler training Development & implementation of an operations plan