

**Mississippi State Penitentiary
Parchman, Mississippi
2018 Sanitation Inspection Report
(June 05-08, 2018)**

Facility Name & Address: Mississippi State Penitentiary Hwy. 49 West Parchman, Mississippi 38728	Inspected By: Rayford Horton, Environmental Admin. I <hr/> INSTITUTIONAL SERVICES P.O. BOX 1700 JACKSON, MISSISSIPPI 39215-1700 PHONE 601/576-7693
Environmental Sanitation	Date of Inspection: June 5-8, 2018
Deficiency	
Unit 29 Bldg. A / Zone A	
Cell 38 no pillow	6/5/2018
Cell 39 commode is clogged	6/5/2018
Cell 40 water pressure too high at lavatory sink (commode doesn't flush properly)	6/5/2018
Cell 24 hole in window screen	6/5/2018
Fire damage to ceiling on upper tier	6/5/2018 (See page 69)
Commode leaking inside the cell	6/5/2018 (See page 68)
Showers contain excessive mold/mildew	6/5/2018 (See page 65 ad 67)
Unit 29 Bldg. A / Zone B	
Upstairs shower no lights	6/5/2018
Cell 66 no screen on window	6/5/2018
Cell 7 hole in window screen	6/5/2018
Cell 71 hole in window screen	6/5/2018
Cell 78 no pillow, no mattress	6/5/2018
Cell 86 hole in window	6/5/2018
Cell 87 hole window screen	6/5/2018
Cell 88 no lights	6/5/2018
Cell 66 no lights	6/5/2018
Cell 68 no lights, no electrical power, no water	6/5/2018
Cell 70 no cold water at lavatory sink	6/5/2018
Cell 71 need light bulbs, no water sprinklers	6/5/2018
Cell 77 lavatory sink does not work	6/5/2018
Cell 79 no water at lavatory sink	6/5/2018
Cell 80 bed frame is bent	6/5/2018
Cell 81 no cold water and hot water pressure is high at the lavatory sink	6/5/2018

Cell 82 lavatory sink does not work, no lights	6/5/2018
Cell 83 toilet barely flush, no electrical power	6/5/2018
Cell 85 window won't close	6/5/2018
Unit 29 Bldg. B / Zone A	
Grass growing on top of entrance building	6/5/2018
Bird nest at the edge of the building	6/5/2018
Cell 23 hole in window screen	6/5/2018
Cell 25 hole in window screen	6/5/2018
Cell 28 hole in window screen, hole in wall	6/5/2018
Cell 29 no mattress	6/5/2018
Cell 30 hole in window screen	6/5/2018
Cell 31 hole in window screen	6/5/2018
Cell 32 hole in window screen	6/5/2018
Cell 34 hole in right wall	6/5/2018
Cell 38 hole in wall by the right side of the door	6/5/2018
Cell 39 no window screen	6/5/2018
Upstairs shower light not working	6/5/2018
Upstairs fan hooked to the light fixture	6/5/2018
Cell 43 no window screen	6/5/2018
Cell 23 no hot water at lavatory sink	6/5/2018
Cell 26 lavatory sink out of order	6/5/2018
Cell 27 window out	6/5/2018
Cell 28 no electrical power, no window screen	6/5/2018
Cell 29 no electrical power, no lights	6/5/2018
Cell 32 no lights	6/5/2018
Cell 35 no hot water at lavatory sink	6/5/2018
Cell 37 sink does not work, no lights	6/5/2018
Cell 7, 9 & 20 no cold water at lavatory sink	6/5/2018
Cell 14 mattress is torn	6/5/2018
Cell 13 need mattress cover	6/5/2018
Cell 2,6,9,12 & 13 no hot water at lavatory sink	6/5/2018
Cells 5 & 9 has no electrical power	6/5/2018
Cell 1 window screen torn	6/5/2018
Cell 3 cold water constantly runs at lavatory sink	6/5/2018
Cell 4 hot water pressure low at lavatory sink	6/5/2018
Downstairs shower leaks and contains mold and mildew	6/5/2018
Water fountain front cover removed	6/5/2018
Floor drain backed up	6/5/2018 (See page 70)
Front entrance contains bird nests	6/5/2018
	6/5/2018

	6/5/2018
	6/5/2018
Unit 29 Bldg. B / Zone B	6/5/2018
Upstairs shower no lights	6/5/2018
Cell 66 no screen on window	6/5/2018
Cell 7 hole in window screen	6/5/2018
Cell 71 hole in window screen	6/5/2018
Cell 78 no pillow, no mattress	6/5/2018
Cell 86 hole in window	6/5/2018
Cell 87 hole in window screen	6/5/2018
Cell 88 leaking from ceiling, no electrical power, lavatory sink out of order	6/5/2018
Cell 67 no window screen, window won't close	6/5/2018
Cell 80 no window screen	6/5/2018
Cell 84 hold in window	6/5/2018
Cell 46 & 58 no hot & cold water at lavatory sink	6/5/2018
Light fixture has exposed wires between cell 60 & 61	6/5/2018
Cell 49 and 57 water pressure low at lavatory sink	6/5/2018
Ceiling removed between cell 54 & 55	6/5/2018
Cell 50, 59 & 65 no hot water at lavatory sink	6/5/2018
Cell 54 has exposed wires	6/5/2018
Downstairs shower inoperable and contains mold and mildew	6/5/2018
Downstairs lavatories do not work	6/5/2018
Concrete floor caving in shower	6/5/2018
Window screens missing throughout zone	6/5/2018
Unit 29 Bldg. C / Zone A	
Window panes missing throughout zone	6/5/2018
Window contains bird nests throughout zone	6/5/2018
Ceiling panel removed	6/5/2018 (See page 30)
Downstairs showers has exposed wires and lights do not work	6/5/2018
Downstairs has (1) inoperable toilet	6/5/2018
Shower 1 hot water valve missing	6/5/2018
Bed 14 and 10 lights missing and has exposed wires	6/5/2018
Pigeons and bird nest present on top of building	6/5/2018
CTQ cell missing cover	6/5/2018
Upstairs showers no lights	6/5/2018
Restrooms no lights	6/5/2018

Cell 94 hole in window screen	6/5/2018
Cell 96 hole in window screen	6/5/2018
Cell 98 no window screen	6/5/2018
Cell 100 hole in window screen	6/5/2018
Cell 104 hole in window screen, bird nest in window	6/5/2018
Cell 109 no window screen	6/5/2018
Cell 110 bird nest in window	6/5/2018
Cell 112 no window screen	6/5/2018
Cell 114 hole in window screen	6/5/2018
Cell 116 hole in window screen	6/5/2018
Cell 120 hole in window screen	6/5/2018
Cell 122 hole in window screen	6/5/2018
Cell 124 hole in window screen	6/5/2018
Cell 126 hole in window screen	6/5/2018
Unit 29 Bldg. C / Zone B	
Downstairs Shower 1 sink hot water do not work	6/5/2018
Downstairs has (1) urinal and (1) commode do not work	6/5/2018
Bed 72 has hole in window screen and light fixture has exposed wires	6/5/2018
Shower 2 sink 1 water constantly running and no hot water knob at lavatory sink	6/5/2018
Shower 1 water pressure low at lavatory sink	6/5/2018
Screen torn between beds 74 and 76 and ceiling falling	6/5/2018
Bed 86 window screen missing	6/5/2018
Bed 88 light fixture has exposed wires	6/5/2018
Window screens need cleaning throughout building	6/5/2018
Exposed wires throughout building	6/5/2018
Pipe cover missing	6/5/2018
Unit 29 Bldg. D / Zone A	
Cell 29 hole in window screen, commode and sink do not work, sink	6/5/2018
Cell 32 hole window screen	6/5/2018
Cell 38 no window screen	6/5/2018
Cell 39 no window screen	6/5/2018
Cell 46 hole in window screen	6/5/2018
Cell 48 no window screen	6/5/2018
Cell 49 hole in window screen, bird nest in window	6/5/2018

Cell 50 no window screen	6/5/2018
Cell 52 no window screen	6/5/2018
Cell 54 hole in window screen, no electrical power	6/5/2018
Cell 56 no window screen, no electrical power	6/5/2018
Cell 58 hole in window screen, no electrical power, no lights	6/5/2018
Cell 59 no window screen	6/5/2018
Cell 60 no window screen	6/5/2018
Cell 62 no window screen	6/5/2018
Cell 64 commode does not work	6/5/2018
Cell 57 no electrical power	6/5/2018
Water fountain do not work	6/5/2018
Water standing in shower	6/5/2018
Bird nest and pigeons present on top of building	6/5/2018
Ceiling falling at entrance door	6/5/2018
Bed 8 window missing and ceiling falling	6/5/2018
Bed 6 and 8 window contain bird nest and window missing	6/5/2018
Bed 20 has hole in window	6/5/2018
Downstairs 2 nd shower do not work	6/5/2018
Water fountain do not work	6/5/2018
Downstairs 1 st urinal stopped up	6/5/2018
Shower lights do not work	6/5/2018
Lights out throughout building	6/5/2018
Window screens need cleaning throughout building	6/5/2018
Bird nest outside window on A-zone	6/5/2018
	6/5/2018
Cell 120 hole in window screen	6/5/2018
Cell 124 hole in window screen	6/5/2018
Cell 126 hole in window screen	6/5/2018
Cell 93 Commode does not work	6/5/2018
Cell 94 Commode does not work	6/5/2018
Cell 95 Commode does not work	6/5/2018
Cell 96 Commode does not work	6/5/2018
Cell 97 Commode does not work	6/5/2018
Cell 98 Commode does not work	6/5/2018
Cell 99 Commode does not work	6/5/2018
Cell 100 Commode does not work	6/5/2018
Cell 101 Commode does not work	6/5/2018
Cell 102 Commode does not work	6/5/2018

Cell 103 Commode does not work	6/5/2018
Cell 104 Commode does not work	6/5/2018
Cell 105 Commode does not work	6/5/2018
Cell 106 Commode does not work	6/5/2018
Cell 107 Commode does not work	6/5/2018
Cell 108 Commode does not work	6/5/2018
Cell 109 Commode does not work	6/5/2018
Cell 110 Commode does not work	6/5/2018
Cell 111 Commode does not work	6/5/2018
Cell 112 Commode does not work	6/5/2018
Cell 113 Commode does not work	6/5/2018
Cell 114 Commode does not work	6/5/2018
Cell 115 Commode does not work	6/5/2018
Cell 116 Commode does not work	6/5/2018
Cell 117 Commode does not work	6/5/2018
Cell 118 Commode does not work	6/5/2018
Cell 119 Commode does not work	6/5/2018
Cell 120 Commode does not work	6/5/2018
Cell 121 Commode does not work	6/5/2018
Cell 122 Commode does not work	6/5/2018
Cell 123 Commode does not work	6/5/2018
Cell 124 Commode does not work	6/5/2018
Cell 125 Commode does not work	6/5/2018
Cell 126 Commode does not work	6/5/2018
Cell 127 Commode does not work	6/5/2018
Cell 128 Commode does not work	6/5/2018
Shower light switch out	6/5/2018
Unit 29 Bldg. D / Zone B	
Exposed wires throughout building	6/5/2018
Window missing throughout building	6/5/2018
Downstairs sink hot water knob stripped	6/5/2018
Panel missing above water fountain	6/5/2018
Downstairs 1 st urinal leaks	6/5/2018
Downstairs shower 1 and 2 missing shower head	6/5/2018
Bed 88 need mattress cover and window screen is torn	6/5/2018
Downstairs 2 nd lavatory sink stopped up and hot water constantly runs	6/5/2018
Cell 42 hole in window screen	6/5/2018
Cell 44 hole in window screen	6/5/2018
Cell 46 hole in window screen	6/5/2018
Cell 48 no window screen	6/5/2018
Cell 60 no window screen	6/5/2018
Mildew upstairs	6/5/2018

Water fountain does not work	6/5/2018
No lights in shower	6/5/2018
Cell 64 hole in wall sink out	6/5/2018
2 nd commode does not work	6/5/2018 (See Page 28)
Cell 59 no window screen	6/5/2018
Cell 58 no window screen	6/5/2018
Unit 29 Bldg. E / Zone A	
Exposed wires throughout building	6/5/2018
Window missing throughout building	6/5/2018
Bed 8 and 16 need mattress	6/5/2018
Downstairs lavatory sink do not work	6/5/2018
Downstairs 1 st urinal and 1 st commode do not work	6/5/2018
Downstairs shower lights do not work	6/5/2018
Downstairs 1 st shower do not work	6/5/2018
Downstairs 1 st lavatory sink water constantly running	6/5/2018
Cell 102 no window screen	6/5/2018
Cell 104 no window screen	6/5/2018
Cell 108 no window screen	6/5/2018
Cell 109 hole in window screen	6/5/2018
Cell 110 no window screen	6/5/2018
Cell 112 no window screen	6/5/2018
Cell 118 no window screen	6/5/2018
Cell 124 no window screen	6/5/2018
Cell 126 no window screen	6/5/2018
Unit 29 Bldg. E / Zone B	
Bed 66 has hole in window screen and need mattress cover	6/5/2018
Bed 69, 77 and 79 need mattress	6/5/2018
Downstairs 1 st commode, 2 nd lavatory and 2 nd urinal do not work	6/5/2018
Downstairs 2 nd shower missing knob	6/5/2018
Bed 74 and 76 missing window screen and lights do not work	6/5/2018
Bed 80 window screen missing	6/5/2018
Light switch cover missing throughout building	6/5/2018
Unit 29 Bldg. F / Zone A	
Inmate on a 10 feet lift in the air with no safety handles and the other inmate pulling the ladder from on location to other location while the lifter was in the air	6/5/2018
Cell 30 bird nest in window	6/5/2018

Cell 32 hole in wall on the left side of wall	6/5/2018
Cell 48 hole in window screen	6/5/2018
Cell 49 hold in window screen, window won't close	6/5/2018
Cell 52 bird nest in window	6/5/2018
Bed 6 and 20 hole in window screen	6/5/2018
Bed 22 window screen missing	6/5/2018
Downstairs shower window has hole in screen	6/5/2018
Downstairs 2 nd shower do not work	6/5/2018
Downstairs 2 nd lavatory sink faucet head missing	6/5/2018
Downstairs 2 nd commode do not work	6/5/2018
Bed 11 and 12 lights in do not work	6/5/2018
Bed 4 light missing	6/5/2018
Bed 15 and 16 light cover missing	6/5/2018
Unit 29 Bldg. F / Zone B	
2 nd toilet out of order	6/5/2018
1 st urinal out	6/5/2018
No lights in restroom	6/5/2018
No lights in shower	6/5/2018
1 st sink out of order in bathroom	6/5/2018
Cell 99 hole in screen	6/5/2018
Cell 108 bird nest in window	6/5/2018
Cell 116 no window screen	6/5/2018
Bed 84 hole in window screen	6/5/2018
Downstairs 1 st shower missing knob	6/5/2018
Downstairs 2 nd urinal do not work	6/5/2018
Bed 87-90 lights do not work	6/5/2018
Window screens need cleaning throughout building	6/5/2018
Exposed wired throughout building	6/5/2018
Division 2 Unit 29	
Unit 29 Bldg. G / Zone A	
Cell 25 hole in wall	6/5/2018
Cell 26 hole in wall	6/5/2018
Cell 39 no pillow	6/5/2018
Cell 33 sink out of order	6/5/2018
Cell 37 no hot water, no electrical power	6/5/2018
Cell 32 water leak, no lights	6/5/2018
Hole in wall between cell 25 and 26	6/5/2018
Cell 29 no lights	6/5/2018

Cell 34 no lights	6/5/2018
Cell 36 window won't close	6/5/2018
Cell 24 hole in window screen	6/5/2018
Bed 3, 8 need mattress	6/5/2018
Cell 2, 4, and 5 no hot water at lavatory sink	6/5/2018
Cell 2 contains mold on wall and rain in cell	6/5/2018
Cell 5 lights do not work and leaks in cell	6/5/2018
Cell 6 has hole in window screen	6/5/2018 (See page 73)
Cell 9 cell floods and hot water knob missing	6/5/2018
Cell 8 leaks in cell	6/5/2018
Cell 18 cold water leaks at lavatory sink	6/5/2018
Cell 16 light do not work	6/5/2018
Cell 14 light switch outside cell not attached to wall	6/5/2018
Cell 11 toilet water pressure low	6/5/2018
Downstairs 1 st shower water constantly run	6/5/2018
Downstairs shower 2 and 3 light do not work	6/5/2018
Unit 29 Bldg. G / Zone B	
Cell 45 no pillow, no mattress	6/5/2018
Cell 46 no pillow, no mattress	6/5/2018
Cell 43 no mattress	6/5/2018
Cell 55 no pillow	6/5/2018
Cell 56 no pillow	6/5/2018
Cell 61 no pillow	6/5/2018
Cell 62 no pillow	6/5/2018
Bed 105, 110 and 113 need mattress	6/5/2018
Cell 17 lavatory sink hot water button is missing and cold water does not work	6/5/2018
Cell 16 cold water button missing	6/5/2018
Cell 17 ceiling paneling is missing above cell	6/5/2018
Cell 12 water leaks from bottom of commode	6/5/2018
Cell 9 window doesn't close, leaks in cell and hole in screen	6/5/2018
Cell 1 lavatory sink hot water does not work and hole in window screen	6/5/2018
Cell 3 hole in window screen and rains through the window	6/5/2018
Cell 6 lavatory sink hot water and electrical power does not work	6/5/2018
Cell 4 window screen torn	6/5/2018
Attic fan do not work	6/5/2018
Downstairs shower 2 and 3 shower head missing	6/5/2018
Shower floor and wall has paint peeling and water will not drain	6/5/2018 (See page 71)

Unit 29 Bldg. H / Zone A	
Cell 28 no cold water, hole in window screen	6/5/2018
Cell 29 lights out, no cold water at lavatory sink	6/5/2018
Cell 30 no lights, hole in wall	6/5/2018
1 st shower do not wok	6/5/2018
Cell 38 no cold water at lavatory sink	6/5/2018
Cell 69 no pillow	6/5/2018
Cell 27 hole in window screen	6/5/2018
Cell 23 hole in window screen	6/5/2018
Cell 1 and 3 hot water constantly run	6/5/2018
Cell 5 exposed wires	6/5/2018
Cell 9 lights do not work, light transom cover missing and lavatory sink cold water does work	6/5/2018
Metal hanging between cell 8 and 9	6/5/2018 (See page 66)
Exposed wires near exit door and exit light sign missing	6/5/2018
Heavy presence of mosquitoes	6/5/2018
Cell 16 hot water knob sticking and light cover missing	6/5/2018
Cell 16 sink leaks	6/5/2018
Shower 1 light does not work	6/5/2018
Shower 2 light does not work and water constantly run at lavatory sink	6/5/2018
Unit 29 Bldg. H / Zone B	
Cell 40 no electrical power	6/5/2018
Cell 26 commode is leaking	6/5/2018
Cell 36 window won't close	6/5/2018
Cell 35 no cold water at lavatory sink	6/5/2018
Cell 34 no cold water at lavatory sink	6/5/2018
Cell 33 no cold water at lavatory sink	6/5/2018
Cell 19 water constantly run	6/5/2018
Cell 17 no hot water at lavatory sink and light does not work	6/5/2018
Cell 16 leaks in cell	6/5/2018
Cell 1 window leaks	6/5/2018
Cell 4 and 5 ceiling leaks	6/5/2018
Cell 7 electrical sockets do not work	6/5/2018
Cell 9 no hot or cold water at lavatory sink	6/5/2018
Unit 29 Bldg. I / Zone A	
Cell 39 no hot water at lavatory sink, no pillow	6/5/2018

Cell 20 commode is leaking	6/5/2018
Cell 23 light switch not working	6/5/2018
Cell 30 no electrical power	6/5/2018
Cell 31 no water pressure at lavatory sink	6/5/2018
Cell 32 no hot water at lavatory sink, no electrical power	6/5/2018
Cell 35 no hot water at lavatory sink, window won't open, no light switch	6/5/2018
Cell 40 no pillow	6/5/2018
Cell 41 no pillow	6/5/2018
Cell 42 no pillow	6/5/2018
Cell 79 no pillow, no mattress	6/5/2018
Cell 1 and 3 water constantly runs at lavatory sinks	6/5/2018
Cell 2 and 5 hot water inoperable	6/5/2018
Cell 6 and 7 buttons sticking on sink	6/5/2018
Bed 11 and bed 17 need mattress	6/5/2018
Cell 9 cold water inoperable and leaks in cell	6/5/2018
Cell 19 hole in window screen	6/5/2018
Cell 18 lavatory sink do not work	6/5/2018
Cell 14 lights and no hot water at lavatory sink	6/5/2018
Cell 12 window will not open	6/5/2018
Cell 11 hot water button sticking	6/5/2018
Downstairs shower 1 light and shower inoperable	6/5/2018
Downstairs shower 3 lights inoperable	6/5/2018
Unit 29 Bldg. I / Zone B	
Cell 57 no pillow, no mattress	6/5/2018
Cell 58 no pillow, no mattress	6/5/2018
Cell 24 no power, light out	6/5/2018
Cell 26 no hot water at lavatory sink, no lights	6/5/2018
Cell 27 no cold water at lavatory sink	6/5/2018
Cell 37 sink stopped up, no hot water at lavatory sink	6/5/2018
Cell 38 sink stopped up, no hot water at lavatory sink	6/5/2018
Cell 21 no light cover	6/5/2018
Cell 25 no lights	6/5/2018
Cell 20 no light cover	6/5/2018
Cell 34 no light switch	6/5/2018
Cell 35 no light switch	6/5/2018
Cell 39 no hot water at lavatory sink	6/5/2018

Cell 2 and 19 no hot and cold water at lavatory sink	6/5/2018
Cell 18 cold water knob missing	6/5/2018
Cell 17 cold water knob sticking	6/5/2018
Cell 16 no electrical power and no hot water at lavatory sink	6/5/2018
Cell 14 no electrical power and leaks in cell	6/5/2018
Cell 13 leaks in cell	6/5/2018
Cell 12 hole in window screen and leaks in cell	6/5/2018
Cell 10 no electrical power	6/5/2018
Cell 1 no cold water at lavatory sink	6/5/2018
Cell 3 no hot water at lavatory sink and sink leaks	6/5/2018
Cell 4 no hot water at lavatory sink	6/5/2018
Downstairs shower 1 shower head missing	6/5/2018
Downstairs shower 2 water constantly run	6/5/2018
Light covers missing throughout building	6/5/2018
Cell 13 electrical switch missing and offender had microwave straight wired	6/5/2018
Unit 29 Bldg. J / Zone A	
Cell 17 no hot water at lavatory sink and no lights	6/5/2018
Cell 14 toilet goes down slow	6/5/2018
Cell 10 need mattress cover	6/5/2018
Cell 3 no cold water at lavatory sink	6/5/2018
Unit 29 Bldg. J / Zone B	
Unit 29 Bldg. K	
Unit 29 Bldg. K / Zone A	
Cell 39 no pillow	6/5/2018
Cell 40 no pillow, no hot water at lavatory sink, no lights	6/5/2018
Cell 41 no pillow	6/5/2018
Cell 42 no pillow	6/5/2018
Cell 43 no pillow	6/5/2018
Cell 44 no pillow, no window screen	6/5/2018
Cell 45 no pillow	6/5/2018
Cell 46 no pillow	6/5/2018
Cell 48 no pillow, no mattress	6/5/2018
Cell 47 no pillow	6/5/2018
Cell 49 no pillow	6/5/2018
Cell 50 no pillow	6/5/2018
Cell 51 no pillow, no mattress	6/5/2018

Cell 26 no pillow, mattress	6/5/2018
Cell 22 no pillow, no window screen	6/5/2018
Cell 52 no pillow, no mattress	6/5/2018
Cell 55 no pillow, no sheets	6/5/2018
Cell 56 no pillow, no bed sheets	6/5/2018
Cell 57 no pillow, no bed sheets	6/5/2018
Cell 58 no pillow, no bed sheets	6/5/2018
Cell 59 no pillow, no mattress	6/5/2018
Cell 62 no pillow, no mattress	6/5/2018
Cell 61 no pillow, no bed sheets	6/5/2018
Cell 63 no mattress	6/5/2018
Cell 64 no mattress	6/5/2018
Cell 69 no bed sheets	6/5/2018
Cell 73 no pillow	6/5/2018
Cell 72 no sheets	6/5/2018
Cell 75 no pillow, no bed sheets	6/5/2018
Cell 76 no pillow, no bed sheets	6/5/2018
Cell 77 no pillow	6/5/2018
Cell 79 no pillow	6/5/2018
Cell 80 no pillow	6/5/2018
Cell 20 no cold water at lavatory sink, no lights	6/5/2018
Cell 25 no cold water at lavatory sink	6/5/2018
Cell 29 commode has a leak	6/5/2018
Dayroom roof leaking	6/5/2018
Cell 32 no lights, no hot water at lavatory sink	6/5/2018
Cell 34 no lights	6/5/2018
Bird nest and feces present above Gate 9	6/5/2018
Cell 18 sediments coming from hot water in sink	6/5/2018
Cell 9 lights and hot water inoperable	6/5/2018
Downstairs shower #41 inoperable	6/5/2018
Cell 1 and 16 window screen has hole	6/5/2018
Bed 1, 9, 10, 11 need mattress	6/5/2018
Cell 2 no hot and cold water at lavatory sink	6/5/2018
Cell 3 no cold water at lavatory sink	6/5/2018
Cell 5 light missing	6/5/2018
Cell 18 no bed sheets and hole in window screen	6/5/2018
Cell 17 water constantly runs at lavatory sink	6/5/2018
Cell 14 and 15 switch plate missing	6/5/2018
Cell 14 leaks around sink and bottom of toilet	6/5/2018
Cell 13 leaks in cell	6/5/2018
Pipe chase leaks between cells 12 and 13	6/5/2018 (See page 72)
Downstairs shower 1 and 2 lights inoperable	6/5/2018
Downstairs shower 3 light inoperable and drain stopped up	6/5/2018
Windows need cleaning throughout	6/5/2018
Wires exposed throughout	6/5/2018

Unit 29 Bldg. K / Zone B	
Cell 119 no pillow	6/5/2018
Cell 120 no pillow	6/5/2018
Cell 121 no pillow	6/5/2018
Cell 129 no pillow	6/5/2018
Cell 130 no pillow, no bed sheets	6/5/2018
Cell 131 no pillow	6/5/2018
Cell 132 no pillow, no mattress	6/5/2018
Cell 141 no pillow, no mattress	6/5/2018
Cell 142 no pillow	6/5/2018
Cell 143 no pillow	6/5/2018
Cell 144 no pillow	6/5/2018
Cell 145 no pillow	6/5/2018
Cell 146 no pillow	6/5/2018
Cell 150 no mattress	6/5/2018
Unit 29 Bldg. L / Zone A	
Cell 79 no pillow	6/5/2018
Cell 39 no pillow	6/5/2018
Cell 40 no pillow, lights out	6/5/2018
Cell 43 no pillow	6/5/2018
Cell 44 no pillow	6/5/2018
Cell 47 no pillow	6/5/2018
Cell 49 no pillow	6/5/2018
Cell 51 no pillow	6/5/2018
Cell 52 no pillow	6/5/2018
Cell 53 no pillow	6/5/2018
Cell 54 no pillow	6/5/2018
Cell 55 no pillow	6/5/2018
Cell 56 no pillow	6/5/2018
Cell 59 no pillow	6/5/2018
Cell 60 no pillow	6/5/2018
Cell 63 no pillow	6/5/2018
Cell 64 no pillow	6/5/2018
Cell 67 no pillow	6/5/2018
Cell 75 no pillow	6/5/2018
Cell 76 no pillow	6/5/2018
Cell 77 no pillow	6/5/2018
Cell 78 no pillow	6/5/2018
Cell 27 sink works when it is kicked	6/5/2018
Top tower covered with bird dropping	6/5/2018

Cell 30 lavatory sink has a leak	6/5/2018
Bed 9 need bed sheets	6/5/2018
Bed 10, 16, 24 need mattress cover	6/5/2018
Bed 22, 23, 25 and 34 need mattress	6/5/2018
Window screens dirty throughout zone	6/5/2018
Cell 13, 15 and 17 hole in window screen	6/5/2018
Cell 12 lavatory sink hot water do not work	6/5/2018
Downstairs showers 1 and 2 lights do not work	6/5/2018
Unit 29 Bldg. L / Zone B	
Cell 22 no cold water at lavatory sink	6/5/2018
Cell 124 no pillow	6/5/2018
Cell 126 no pillow	6/5/2018
Cell 128 no pillow	6/5/2018
Cell 138 no pillow	6/5/2018
Cell 140 no pillow	6/5/2018
Cell 142 no pillow	6/5/2018
Cell 144 no pillow	6/5/2018
Cell 146 no pillow	6/5/2018
Cell 154 no pillow	6/5/2018
Cell 18 lavatory sink do not work	6/5/2018
Cell 15 lights do not wok	6/5/2018
Cell 10 water ping pong from upstairs	6/5/2018
Bed 84,86,88,90,92 and 93 need mattress	6/5/2018
Cell 1 water leaks in cell	6/5/2018
Exit door has mold	6/5/2018
Downstairs shower 1 lights do not work	6/5/2018
Downstairs showers 2 and 3 do not work	6/5/2018
UNIT 29 Kitchen	
No sanitizer in prep area bucket	6/6/2018
A pack of bologna underneath serving line warmer #2	6/6/2018
Dry milk torn open in dry storage	6/6/2018
Three (3) compartment sink improperly set up	6/6/2018
Roach crawling up wall on food line	6/6/2018
Urinal in kitchen bathroom out-of-order with no sign	6/6/2018

Unit 29 Gym	
1 st urinal do not work	6/5/2018
1 lavatory sink do not work	6/5/2018
1 light is out	6/5/2018

Area II
(Units 25, 26A-B & Kitchen, 28, 30A-D, 30 Gym, Education, 31, 42)

Environmental Sanitation	Date of Inspection: June 05-06, 2018
DEFICIENCY	
MSP Unit #25	
A-zone	
Bed 3 and 13 window screen torn	6/6/2018
Room 60-63 (2) lights do not work	6/6/2018
Exhaust fan do not work	6/6/2018
1 st commode do not work	6/6/2018 (See page 37)
2 nd and 4 th lavatory sinks do not work	6/6/2018 (See page 29)
2 nd right shower do not work	6/6/2018
2 nd and 3 rd left showers do not work	6/6/2018
Urinal do not work	6/6/2018 (See page 35)
B-zone	
Bed 110 torn window screen	6/6/2018
Bed 117 lights do not work and wires exposed	6/6/2018
Exhaust fan do not work	6/6/2018
Window needs cleaning throughout zone	6/6/2018
2 nd commode do not work	6/6/2018 (See page 32)
Urinal does not work	6/6/2018 (See page 31)
2 nd and 3 rd right showers do not work	6/6/2018
3 rd left shower do not work	6/6/2018

Shower drain cover missing	6/6/2018 (See page 34)
Shower ceiling has large hole	6/6/2018 (See page 36)
3 rd lavatory sink missing pipes	6/6/2018 (See page 33)
Exposed wires running from ceiling	6/6/2018 (See page 46)
C-zone	
2 showers working out of 6	6/6/2018
3 rd commode does not work	6/6/2018
Urinal hanging off wall	6/6/2018
Bed 123 no mattress	6/6/2018
Bed 135 no window screen	6/6/2018
Bed 169 hole in screen	6/6/2018
Bed 179 rusty sheets	6/6/2018
Bed 177 no pillow	6/6/2018
Bed 173 no pillow, rusty sheets	6/6/2018
Bed 189 no light bulbs in light fixture, no window screen	6/6/2018
Cube 154 no light bulbs in light fixture	6/6/2018
Cube 167 lights do not work	6/6/2018
Cube 172 lights do not work	6/6/2018
Cube 155-160 3 lights do not work	6/6/2018
Hole in wall by water fountain	6/6/2018
Bed 190 hole in window screen	6/6/2018
Bed 205 no window screen	6/6/2018
Bed 211 no window screen	6/6/2018
Bed 230 no window screen	6/6/2018
D-Zone	
4 th sink in bathroom leaking	6/6/2018
2 showers out of 6 working	6/6/2018
No exit sign at backdoor	6/6/2018
Cube 193-198 three (3) lights do not work, no window screen	6/6/2018
Cube 215- 220 no window screen	6/6/2018
Bed 217 no pillow	6/6/2018
Bed 220 no pillow	6/6/2018
Bed 221- 226 1 light working out of 4	6/6/2018
Zone exhaust fan does not work	6/6/2018
FOOD SERVICE SANITATION-Unit 25 Kitchen	
Hole inside facing of door	6/6/2018
Blower fan does not work	6/6/2018
Dish washer not sanitizing	6/6/2018
Flies present in kitchen	6/6/2018
Small ice machine has brown substance and needs cleaning	6/6/2018

MSP Unit #26 A Building	
A-Zone	
2 nd and 6 th shower do not work	6/6/2018
Bed 10 no window screen	6/6/2018
Bed 8 no wall socket cover	6/6/2018
Commode does not work	6/6/2018 (See page 50)
B-Zone	
Bed 65 bird nest in window	6/6/2018 (See page 51)
Beds 107-111 lights do not work	6/6/2018
Bed 108 wall socket out	6/6/2018
Water fountain do not wok	6/6/2018
Zone exhaust fan do not work	6/6/2018
2 nd shower do not work	6/6/2018
3 rd lavatory sink do not work	6/6/2018
1 st and 2 nd urinals do not work	6/6/2018 (See page 52)
C-Zone	
Hole in wall over left middle shower	6/6/2018 (See page 38)
(3) shower heads missing	6/6/2018
Bed 136 window screen torn	6/6/2018
(4) showers d not work	6/6/2018
Bed 165 bird nest in window	6/6/2018 (See page 41)
Water fountain do not work	6/6/2018
2 nd commode does not work	6/6/2018
5 th lavatory sink contained bologna	6/6/2018 (See page 39)
Bed 122 window screen needs cleaning	6/6/2018
Window screens missing throughout zone	6/6/2018
D-Zone	
Bed 172 had bird nest in window	6/6/2018
Bed 221 hole in window screen	6/6/2018
Bed 212 need mattress	6/6/2018
1 st commode has a leak and 2 nd commode do not work	6/6/2018 (See page 40)
E-Zone	
2 nd bathroom lavatory sink does not work	6/6/2018 (See page 42)
Heaters in hall area with (1) sparking fire	6/6/2018
3 rd bathroom 1 st and 2 nd commode and 2 nd lavatory sink inoperable	6/6/2018
3 rd commode has no seat cover	6/6/2018
1 st left shower knob missing	6/6/2018
Middle shower does not work	6/6/2018
Water leaking from shower wall into laundry room	6/6/2018

MSP Unit #26 B Building	
Pipes leak underneath the canopy	6/6/2018 (See page 54)
Zone-A	
4 th shower does not wok	6/6/2018
1 st commode does not work	6/6/2018
1 st urinal does not work	6/6/2018
Water fountain does not work	6/6/2018
Bed 12 bird nest in window	6/6/2018
Bed 13 rusty sheets	6/6/2018
Bed 17 bird nest in window	6/6/2018
Bed 24 hole in window screen	6/6/2018
Zone-B	
5 th shower does not work	6/6/2018
1 st urinal does not work	6/6/2018 (See page 49)
1 st commode does not work	6/6/2018
Water fountain does not work	6/6/2018
Bed 88 bird nest in window	6/6/2018
Bed 52 no wall electrical socket cover	6/6/2018
Zone-C	
Water leaking on walk way	6/6/2018
Bed 115 mattress torn	6/6/2018
2 nd lavatory sink do not work	6/6/2018 (See page 44)
1 st and 2 nd urinals do not work	6/6/2018
1 st right shower do not work	6/6/2018
Zone-D	
Bed 165 bird nest in window	6/6/2018
Bed 181 window screen torn	6/6/2018
Bed 198 need mattress	6/6/2018
2 nd urinal do not work	6/6/2018
4 th commode do not work	6/6/2018
1 st right shower missing head	6/6/2018
2 nd right shower missing knob	6/6/2018
3 rd left shower does not work	6/6/2018
Zone-E	
1 st commode has a leak	6/6/2018 (See page 45)
Inmate dayroom dirty	6/6/2018

1 st and 2 nd showers do not work	6/6/2018
Bed 256 has no pillow	6/6/2018
Wall socket missing in boiler and ice room	6/6/2018
Ceiling tile missing in dayroom and chemical room	6/6/2018
Cube 255-276 missing ceiling tile	6/6/2018
Water leaks through the wall	6/6/2018 (See page 47and 48)
Unit 26 Kitchen-FOOD SERVICE SANITATION	
Homemade strainer in kitchen dishwasher	6/6/2018
Trays improperly stored	6/6/2018
Air unit has large hole	6/6/2018
Mice dropping inside of grits in storage room	6/6/2018 (See page 53)
Water fountain do not work	6/6/2018
Unit 26 Barber Shop	
Good	
UNIT 28	
Zone A	
Room 29-32 bird nest in window	6/6/2018
Room 35-40 leaking around to commode button	6/6/2018
1 st and 2 nd right shower knob missing	6/6/2018
2 nd left shower knob missing	6/6/2018
	6/6/2018
Zone B	
Hole in wall above water fountain	6/6/2018
Water fountain does not work and wall has a hole above the fountain	6/6/2018 (See page 56)
Room 81-84 commodes are leaking	6/6/2018
Window screens missing throughout zone	6/6/2018
Room 69-72 toilet knob leaks water	6/6/2018
2 nd left shower and 1 st right shower do not work	6/6/2018
Zone C	
2 nd shower do not work	6/6/2018
Lavatory sinks 2 and 7 are leaking, need light bulb over sink	6/6/2018
Bed 123 bird nest in window	6/6/2018
Bed 133 no window screen	6/6/2018

Zone D	
2 showers do not work	6/6/2018
Bed 40 1 light out	6/6/2018
Bed 178 bird nest in window	6/6/2018
Bed 179 bird nest in window	6/6/2018
Bed 35 small hole in wall by the commode flush button	6/6/2018
Hole on side of the water fountain	6/6/2018
Unit 28 Kitchen-FOOD SERVICE SANITATION	
Ice machine needs cleaning	6/6/2018
No paper towels are soap for hand wash sink	6/6/2018
Wet dish towels left on serving line	6/6/2018
Flies present in kitchen	6/6/2018
Apple sauce in cooler without a date	6/6/2018
Standing water in bottom of cooler containing a dead fly	6/6/2018 (See page 58)
Leak under 3-compartment sink	6/6/2018 (See page 59)
Vents need cleaning throughout dining hall	6/6/2018 (See page 57)
Unit 28 Barber Shop	
Good	
MSP Unit #30 A Building	
Zone A	
Bed31,32,46,59,63,71,77,56,94,89,106,105, and 108 need mattress	6/7/2018
Bed 57 and 92 sheets are rusty	6/7/2018
Bed 16,69,98,95 and 82, mattress torn	6/7/2018
Bed 104,101,92,99,and 82 need sheets	6/7/2018
Pillows missing throughout zone	6/7/2018
3 rd lavatory sink cold water do not work	6/7/2018
1 st and 2 nd commode do not work	6/7/2018 (See page 43)
1 st urinal do not work	6/7/2018
Commode on back wall do not work	6/7/2018 (See page 62)
2 nd shower do not work	6/7/2018
4 th shower do not work	6/7/2018
Zone B	
Bed 136,182,173,214,111,123,129 and 131 need mattress	6/7/2018
Bed 166 sheets are rusty	6/7/2018
Bed 139,176,70,168,163,161 and 215 need mattress cover	6/7/2018
Pillows missing throughout zone	6/7/2018
More fans are needed for zone and coolers	6/7/2018

1 st , 2 nd , 3 rd , 5 th , 7 th , and 8 th lavatory sinks do not work	6/7/2018
1 st urinal is missing from the wall	6/7/2018
3 rd urinal do not work	6/7/2018
1 st commode do not work	6/7/2018
4 th commode missing from wall	6/7/2018
5 th commode do not work	6/7/2018
Water fountain constantly run	6/7/2018
3 rd shower do not work	6/7/2018
Shower floor is tiles	6/7/2018 (See page 55)
MSP Unit #30 B Building	
A-Zone	
Bed 85,24,29,31,35,40,49,33,79,19,105,106,108,89 and 94 needs mattress	6/7/2018
Bed 85 sheets are rusty	6/7/2018
Beds 102,1,5,16,59,69,73,96,98,95, and 82 mattress torn	6/7/2018
Bed 104, 101,99,92 and 82 need sheets	6/7/2018
No hot water throughout zone	6/7/2018
Pillows missing throughout zone	6/7/2018
2 nd , 4 th , and 6 th lavatories do not work	6/7/2018
3 rd , 4 th , and 5 th commodes do no work	6/7/2018
Commode on back right wall does not work	6/7/2018
1 st , 2 nd , and 3 rd showers do not work	6/7/2018
Shower ceiling is falling down	6/7/2018
Shower floor missing tile	6/7/2018 (See page 63and 64)
Multiple zone lights are out	6/7/2018
Bed 107 no electrical light switch	6/7/2018
Bed 108 no electrical light switch	6/7/2018
Exposed wires coming from the electrical socket near microwave	6/7/2018
Water fountain missing	6/7/2018
Showers 2, 3, 4 and 6 do not work, ceiling falling	6/7/2018
Sinks 4, 5, 6, and 7 do not work in bathroom	6/7/2018
3 rd urinal does not work	6/7/2018
Commodes 2, 5, and 6 do not work	6/7/2018
Cover missing off wall electrical socket	6/7/2018
B-Zone	

Bed 162 has rusty bed sheets	6/7/2018
Bed 146 has rusty bed sheets	6/7/2018
Commodes 4 and 6 do not work, wall electrical socket cover missing in bathroom	6/7/2018
Showers 1, 3 and 6 do not work	6/7/2018
Exposed wires outside bed 215 and 216 by microwave	6/7/2018
Beds 132,131,134,133,129,186,181,179,172,174,167,196, 111,123,129 and 131 need mattress	6/7/2018
Beds 193 and 189 has rusty sheets	6/7/2018
Beds 139, 137, 156, 121,123 185, 193, 201 and 110 mattress torn	6/7/2018
Beds 150,145,141,135 and 136 need mattress cover	6/7/2018
Bed 184 need new bed	6/7/2018
Pillows missing throughout zone	6/7/2018
4 th and 8 th lavatory sinks do not work	6/7/2018
Hot water does not work at any lavatory sinks	6/7/2018
2 nd commode do not work	6/7/2018
1 st urinal is missing from wall	6/7/2018
2 nd and 3 rd urinal water pressure low	6/7/2018
3 rd lavatory sink has leak	6/7/2018
Commode on right back wall does not work	6/7/2018
MSP Unit #30 D Building	
A-Zone	
Showers 2 and 5 do not work, roof leaking	6/7/2018
Lavatory Sinks 1, 4 and 6 do not work	6/7/2018
4 th commode does not wok	6/7/2018
3 rd urinal does not work	6/7/2018
Several zone lights are out	6/7/2018
Bed 19-21 roof leak when it rains, hole in wall	6/7/2018
Wires plugged in back of zone loose	6/7/2018
Inmates complaining about termites on zone	6/7/2018
	6/7/2018
B-Zone	
Zone lights and security lights are out	6/7/2018
Commodes 1, 3 and 4 do not work	6/7/2018
Light switch and wall socket out in bathroom	6/7/2018
Lavatory Sinks 1, 3 and 4 do not work	6/7/2018
6 th commode is missing from the wall	6/7/2018
Water fountain near shower missing	6/7/2018
Showers 2, 4 and 6 do not work	6/7/2018
Beds 213-216 lights do not work	6/7/2018

FOOD SERVICE SANITATION-30 Kitchen	
Food truck containing milk not on ice at 59 degrees temperature	6/7/2018
Cooler #1 in break room area fan is frozen	6/7/2018
Food disposal leaking in dishwashing room	6/7/2018
MSP Unit #30 ABE	
MSP Unit #30 A&D School	
1 st and 3 rd urinals in the inmate bathroom do not work	6/7/2018
MSP Unit #30 Gym	
(2) lights do not work	6/7/2018
Hot water does not work	6/7/2018
4 th commode do not work	6/7/2018
2 nd , 3 rd , 4 th and 5 th lavatory sinks do not work	6/7/2018
MSP Unit #31	
A-Zone	
B-Zone	
C-Zone	
Room 149 (5) lights do not work	6/7/2018
Mold and mildew and paint peeling in shower ceiling	6/7/2018 (See page 61)
3 rd shower does not work	6/7/2018
Screen missing throughout zone	6/7/2018
1 st lavatory sink does not work	6/7/2018 (See page 60)
D-Zone	
2 nd lavatory sink do not work	6/6/2018
2 nd commode do not work	6/6/2018

MSP Unit #31 Food Sanitation	
20 oz. Coke, coffee mug and personal food inside of cooler	6/6/2018
No sanitizer in dishwasher	6/6/2018
Using ice in pans on serving line to keep milk cold	6/6/2018
MSP Unit #42 - Hospital	
Kitchen	
Ice machine needs cleaning	6/7/2018
Milk sitting on ice machine not on ice	6/7/2018
Exposed wires under steam table	6/7/2018
Steam table inoperable	6/7/2018
Dishwasher not sanitizing	6/7/2018
Laundry	
Lint build up in lint tray and dryer	6/7/2018
Cleaning needed behind washer and dryer	6/7/2018
Westward	
Isolation 1 shower head broken	6/7/2018
Isolation 2 sink and commode do not work	6/7/2018
Southward	
Offender bath toilet won't flush	6/7/2018
Room 210 lights out	6/7/2018
Room 212 light fixture broke, light switch broke off wall	6/7/2018
Room 213 lights work on inside, but not on the outside	6/7/2018
Room 214 lights not working inside nor	6/7/2018

outside	
Room204 lights not working outside	6/7/2018
Room 203 dual glass need repairing	6/7/2018
Room 202 dual glass need repairing	6/7/2018
Eastward	
Commode do not work	6/7/2018
dual glass need repairing	6/7/2018

(Unit 32 Central Laundry, Vo-Tech Kitchen)

Environmental Sanitation	Date of Inspection: June 08, 2017
Deficiency	
MSP Unit #32-Laundry	
Washer 5 and 6 do not work	6/8/2018
Dryer 10 and 8 do not work	6/8/2018
Staff bathroom has continuous flush	6/8/2018
Light switch missing cover exposed wires	6/8/2018
Heater will not shut off	6/8/2018
Vocational School	
Good	6/8/2018
Processing Kitchen	
Closed	
Cold Storage	
Good	
Metal Fab Building	
Closed	



**Unit 29 Bldg. D (Zone B)
2nd Commode does not work**



**Unit 25 (Zone A)
2nd and 4th lavatory sinks do not work**



**Unit 29 Bldg. C (Zone A)
Ceiling panel has been removed**



**Unit 25 (Zone B)
Urinal does not work**



**Unit 25 (Zone B)
2nd commode does not work**



**Unit 25 (Zone B)
3rd lavatory sink is missing pipes**



**Unit 25 (Zone B)
Shower drain cover is missing**



**Unit 25 (Zone A)
Urinal does not work**



**Unit 25 (Zone B)
Shower has a hole in the ceiling**



**Unit 25 (Zone A)
1st commode does not work**




**Unit 26 Bldg. A (Zone C)
Holes in wall over left middle shower**



**Unit 26 Bldg. A (Zone C)
5th lavatory sink contained bologna**



Unit 26 Bldg. A (Zone D)
1st commode has a leak and 2nd commode does not work



**Unit 26 Bldg. A (Zone C)
Bed 165 has a bird nets in the window**



**Unit 26 Bldg. A (Zone E)
2nd lavatory sink does not work**



**Unit 30 Bldg. A (Zone A)
1st and 2nd commodes do not work**



**Unit 26 Bldg. B (Zone C)
2nd lavatory sink does not work**



**Unit 26 Bldg. B (Zone E)
1st commode has a leak**



**Unit 25 (Zone B)
Exposed wires running from the ceiling**



**Unit 26 Bldg. B (Zone E)
Water leaks through the wall**



**Unit 26 Bldg. B (Zone E)
Water leaks through the wall**



**Unit 29 Bldg. B (Zone B)
1st urinal does not work**



**Unit 26 Bldg. A (Zone A)
Commode does not work**



**Unit 26 Bldg. A (Zone B)
Bed 65 has a bird nest in the window**



**Unit 26 Bldg. A (Zone B)
1st and 2nd urinals do not work**



**Unit 26 Kitchen Storage
Mice droppings inside the bag of grits**



**Unit 26 Bldg. B (Zone A)
Pipes leak underneath canopy**



**Unit 30 Bldg. A (Zone B)
Shower floor has missing tiles**



**Unit 28 (Zone B)
Water fountain does not work and the wall has a hole in it**



**Unit 28 Kitchen
Vents in the dining hall needs cleaning**



**Unit 28 Kitchen
Standing water in bottom of cooler with dead flies**



**Unit 28 Kitchen
Leak underneath 3 compartment sink**



**Unit 31 (Zone C)
1st lavatory sink does not work**



Unit 31 (Zone C)
Shower ceiling has mold/mildew and paint peeling



**Unit 30 Bldg. A (Zone A)
Commode on back wall does not work**



**Unit 30 Bldg. B (Zone A)
Shower floor has missing tiles**



**Unit 30 Bldg. B (Zone A)
Shower floor has missing tiles**



**Unit 29 Bldg. A (Zone A)
Showers contain mold/mildew**



**Unit 29 Bldg. H (Zone A)
Ceiling panel metal is hanging between cells #8 and #9**



**Unit 29 Bldg. A (Zone A)
Showers contain mold/mildew**



**Unit 29 Bldg. A (Zone A)
Commode leaking inside the cell**



**Unit 29 Bldg. A (Zone A)
Fire Damage to the ceiling**



**Unit 29 Bldg. B (Zone A)
Floor drains backed up and overflowing into the zone**



Unit 29 Bldg. G (Zone B)
Shower has paint peeling, broken concrete floor and water will not drain



**Unit 29 Bldg. K (Zone A)
Pipe chase leaks water between cells #12 and #13**



**Unit 29 Bldg. G (Zone A)
Window screen has holes**